



NOTE: This reset sheet is ONLY for the Intermec 1800 ScanPlus scanner. Please verify your scanner looks like the above image.

To reset your scanner to the default settings for use with Systems Design scan the following two bar codes.

Step 1

Default setup

Read this code to reset your scanner to the default configuration



Step 2

QWERTY US English

